03/23/94

MINE ID: M0450017

MINE NAME: MERCUR MINE

BLM #:

OPERATOR: BARRICK MERCUR GOLD MINES, INC

CONTACT: DAVID P. BEATTY ADDRESS: P O BOX 838

TOOELE UT 84074

PHONE: (801)268-4447

Surface Owner: PRIVATE Lease #: Mineral Owner: PRIVATE

Qtr-Qtr-Qtr1 Qtr-Qtr1 Qtr-Qtr-Qtr2 Qtr-Qtr2 Qtr2 Town Range Sec 3.0W 6.0S 4 3.0W 6.0S 8 3.0W 32 5.0S

Mine Type [(S)urface, (U)nderground]: S Permit Status: APP

Mine Status (PRO,ACT,SUS,RET): ACT

Acreage: 850

Minerals Mined AU. AG

LAST INSPECTED FINAL APPROVAL TENTATIVE APPROVAL DATE DATE DATE RECEIVED 07/13/93 10/13/81 05/01/81 03/10/81

BOND TYPE: SELF BOND

BOND AMOUNT: \$\$8,808,891

## ANNUAL REPORT YEAR: 93

NONCOMP NOTICES: VIOLATIONS: REVISIONS:	0	Total 0 0 0	DATE ISSUED: / / DATE ISSUED: / / DATE REC'D: / / DATE REC'D: 03/11/92	DATE RESOLVED: / / DATE RESOLVED: / / DATE APPROVED: / / DATE APPROVED: 05/18/92
AMENDMENTS:	0	1	DATE REC'D: 03/11/92	DATE APPROVED: 05/10/92

INSPECTION MADE TO EVALAUTE AREAS RECENTLY RECLAIMED & TO PROPOSE RECLAMATION COMMENTS: TECHNIQUES FOR DIFFICULT AREAS. BARRICK ATTEMPTED TO CAST TOPSOIL ONTO SNIDER DUMP, BUT WAS NOT SUCCESSFUL. DUMP TOO STEEP & SOIL SLID TO BOTTOM OF DUMP. TOP & UPPER PORTION OF THE SLOPES HAVE FORMED A DURABLE CRUST DUE TO THE CLAY CONTENT OF THE DUMP MATERIAL. CANNOT REGRADE THE DUMP TO A 2:1 BECAUSE IT MAY PLACE MATERIAL ON THE MAIN ACCESS ROAD BELOW. NORTH MERCUR DUMP IS AT ANGLE OF REPOSE & HOLDING HYDROMULCH MIX QUITE WELL. SNIDER DUMP NEEDS MORE INSPECTION.